



Suggested Installation Instructions for:
602-121, 1963-1982 Power Window Motor Gear and Bushing
602-123, 1968-1982 Shaft Bushing

(IMPORTANT NOTE)

PLEASE READ BEFORE INSTALLATION OR DAMAGE WILL RESULT

PLEASE READ VERY CAREFULLY — VERY IMPORTANT:

If you are replacing the regulator because of stripped gears, you must do one or both of the following:

- 1) Replace window motor gears—See Figure #1
- 2) Replace bushing in mounting plate—See Figure #2

If either or both of the above is not completed, damage will result voiding any warranty.

BEFORE INSTALLATION:

You must check power window motor gear (Fig. 1) to make sure gears are good. Check bushing (Fig. 2) on mounting plate. If any wear exists, your new regulator gear teeth (Fig. 3) may be damaged. Check for proper alignment of motor in the regulator (3 holes). The shoulder of motor should go through the regulator holes. Grease ALL tracks and rollers.

AFTER INSTALLATION:

Before installing door panel, run window up and down a few times. Check teeth alignment to make sure gear teeth are properly engaged.

IMPORTANT NOTE: REGULATOR MUST BE GROUNDED OR WINDOW MOTOR WILL NOT OPERATE.

PART NUMBERS:

602-121 (162656)-Power Window Motor Gear
 602-123 (162700)-Bushing

Figure #1




PW Motor Gear

Figure #2



Mounting Plate

Figure #3



Regulator Gear